TMT130 Temperature Transmitter, +/-0.1 degC (+/-0.18 degF), 0...10 V

Type	Options	1	2	3	4	5	6	7	8	9	10	11	12	13	14
Measurement Type	Temperature, HMP110T Stainless Steel Probe	A													
	TMP115 3m, with 5-point calibration -90, -45, 0, +45, +90 °C	B													
	TMP115 3m, with 6-point calibration -196,-90,-45, 0,+45, +90 °C	C													
Probe Details	Probe Mounted on Transmitter (Stainless Steel Probe)		A												
	3 m Cable for Remote Probe		B												
	5 m Cable for Remote Probe		C												
	10 m Cable for Remote Probe		D												
	10 m with Cable for Remote Probe with 10m Extension Cable		E												
	20 m Cable for Remote Probe		F												
	1,2 m Remote Probe Cable		G												
	TMP115 Mounted on Transmitter		M												
Display	No Display			0											
	With Display			1											
Analog Output Signal	Output 0...1 V				B										
	Output 0...5 V				C										
	Output 0...10 V				D										
	Special Output				X										
Parameter for Ch1	T -40...+60 °C (-40...+140 °F)					B									
	T -20...+80 °C (-4...+176 °F)					C									
	T 0...+60 °C (+32...+140 °F)					D									
	Temperature Range T -40...+80 °C (-40...+176°F)					E									
	Temperature Range T 0...+50 °C (+32...+122°F)					F									
	Temperature Range T -90 … 0 C (-130...+ 32°F)					G									
	Temperature Range T -90 … +30 C (-130...+ 86°F)					H									
	Temperature Range T -200 … +0 C (-328...+ 32°F)					J									
	Channel 1 Parameter and Custom Scaling					X									
Parameter for Ch2	Channel 2 No Output						A								
Additional Module	No Module							0							
Display Units	Metric Units								1						
	Non Metric Units								2						
Sensor Protection	Plastic Grid for Steel Probe									1					
	Plastic Grid with PTFE filter for Steel Probe									2					
	Stainless steel sintered filter									3					
	Sintered Teflon Filter for Steel Probe									E					
	TMP115 sensor									N					
Transmitter Installation	No Accessories										A				
	Rain Shield with Installation Kit										C				
Installation Kit for Probe	No Accessories											1			
	Duct Installation Kit											2			
	Probe Mounting Flange											3			
	Solar Radiation Shield with Probe Installation Kit											5			
	Probe Mounting Clamp											6			
	Magnetic probe holder											7			
Cable Bushings	Cable Gland for 2...6 mm Diameter Cable												A		
	Conduit Fitting PG9												B		
	Conduit Fitting NPT 1/2"												C		
	No Bushing (with rubber plug)												D		
	All Bushings (Includes Cable Gland, PG9 and NPT1/2" Conduit Fittings)												Z		
PC Accessories	No Accessories													0	
	USB Service Cable for PC													1	
Operation Manual Language	No User's Guide														A
	Multilingual Manual HMT130														Z