




Fiber optic through beam sensor

FE-11-EPA-M3/F1X1/2M



Application		
Function principle		Through-beam sensor
Application		For use in industrial environments
Monitoring range		
Range with fiber optic amplifier type		OB50; OBF; OCF; OO50
OB50		
Range of fiber optics	[mm]	200
OBF		
Range of fiber optics	[mm]	350
OCF (High Power)		
Range of fiber optics	[mm]	4000
OO50		
Range of fiber optics	[mm]	800
Operating conditions		
Ambient temperature	[°C]	-40...70
Mechanical data		
Weight	[g]	47
Version of sensing head		straight
Sensing head thread		M3

E20603



Fiber optic through beam sensor

FE-11-EPA-M3/F1X1/2M

Sensing head length	[mm]	20
Total length	[mm]	2000
Min. bending radius	[mm]	30
Fiber arrangement		
Core diameter	[mm]	1
Fiber material		PMMA
Fiber head material		aluminum
Fiber sheath material		PE

Accessories

Items supplied	Hexagon nuts: 4 x M3 tooth lock washers: 4
Accessories (optional)	Cutter for fibers:, E20600

Remarks

Pack quantity	1 pcs.
---------------	--------