



HMP110REF Humidity and Temperature Constant Output Probe

Type	Options	1	2
Humidity Output	Humidity 0%RH	A	
	Humidity 50%RH	B	
	Humidity 100%RH	C	
	Humidity 85%RH	D	
	Custom Humidity	X	
Temperature Output	Temperature -40°C		0
	Temperature +20°C		1
	Temperature +60°C		2
	Custom Temperature		X