



**HMT330MIK Meteorological Installation Kit**

Type	Options	1	2	3	4	5
Support bar & shield for warmed Td probe	No Crossarm or Wind Transmitter	0				
	Support bar for heated RH probe or Td probe	1				
Support bar and radiation shield	No Sensor		A			
	Support bar and DTR502 for additional T probe		B			
	Support bar and DTR13 for T probe		C			
	Support bar and DTR502 for RH/Td probe		D			
	Support bar with DTR13 shield for non-warmed RH/Td probe, or additional T-probe		E			
Support bar mounting plate	No Accessories			0		
	Pole mounting plate for HMT330MIK support bars			1		
Transmitter mounting plate	No Accessories				A	
	Support Bar Mounting for MIK transmitter				B	
	Mik Transmitter Mounting plate for pole assembly				C	
Static Pressure Head	No Pressure Port					0
	Static pressure head SPH10-1					1