



INDIGO201 Analog Output Transmitter

Type	Options	1	2	3	4	5
Display	No Display	0				
	Display With Metric Units	1				
	Display With Non-metric Units	2				
Analog Output Settings	4...20 mA		A			
	0...20 mA		B			
	0...1 V		C			
	0...5 V		D			
	0...10 V		E			
	1...5 V		F			
Cables	No Probe Cable			0		
	Remote Probe Cable, 1m			1		
	Remote Probe Cable, 3m			2		
	Remote Probe Cable, 5m			3		
	Remote Probe Cable, 10m			4		
External Power Supply	No Power Supply				A	
	Universal mains power supply with EU/US/UK/AUS plugs				B	
Customization	NO Customization					0